EAST Search History

Ref	Hits	Search Query	DBs	Default Operator	Plurals	Time Stamp
.1	337	non-destructive and test\$3 and nuclear adj reactor	US-PGPUB; USPAT; EPO; JPO; DERWENT; IBM_TDB	OR	ON	2009/04/06 15:28
2	98	(("(20070248239") or ("5411340") or ("5510910") or ("5883632") or ("6128022") or ("5946426") or ("4975738") or ("4995061") or ("4999716") or ("5028935") or ("5224179") or ("5283684") or ("5305521") or ("5347600") or ("5361098") or ("5430878") or ("5434956") or ("5450533") or ("5467135") or ("5489782") or ("5528493") or ("5570433") or ("5594815") or ("5600407") or ("5673207") or ("5714989") or ("5729008") or ("5754704") or ("5847711") or ("5852671") or ("5995661") or ("6002782") or ("6260764") or ("6299062") or ("6361714") or ("6438168") or ("6438251") or ("6731756") or ("6529630") or ("6539127") or ("6683974") or ("6690485") or ("6724921") or ("6731756") or ("6835110") or ("6934405") or ("7034820") or ("7061030") or ("7061564).pn.")).PN.	US-PGPUB; USPAT; EPO; JPO; DERWENT; IBM_TDB	OR	OFF	2009/04/06 15:31
3	96	L2 and(@ad<"20031124" or @rlad<"20031124" or @prad<"20031124" or @prad<"20031124" or @ptad<"20031124")	US-PGPUB; USPAT; EPO; JPO; DERWENT; IBM_TDB	OR	ON	2009/04/06 15:32
4	0	L3 and non-destructive and test\$3 and nuclear adj reactor	US-PGPUB; USPAT; EPO; JPO; DERWENT; IBM_TDB	OR	ON	2009/04/06 15:32
5	0	L3 and(acquiring or obtaining)near2 radiographic adj image\$1	US-PGPUB; USPAT; EPO; JPO; DERWENT; IBM_TDB	OR	ON	2009/04/06 15:33
6	0	L3 and(acquiring or obtaining)and radiographic adj image\$1	US-PGPUB; USPAT; EPO; JPO; DERWENT; IBM_TDB	OR	ON	2009/04/06 15:33

.7	0	L3 and(test\$3 or inspect\$3 or examining)and(detect\$3 or determining)and(defect or flaw or fault)and welding adj joints	US-PGPUB; USPAT; EPO; JPO; DERWENT; IBM_TDB	OR	ON	2009/04/06 15:34
.8	0	L3 and nuclear adj fuel and rods	US-PGPUB; USPAT; EPO; JPO; DERWENT; IBM_TDB	OR	ON	2009/04/06 15:34
9	0	L3 and nuclear adj fuel	US-PGPUB; USPAT; EPO; JPO; DERWENT; IBM_TDB	OR	ON	2009/04/06 15:35
10	2	L3 and nuclear	US-PGPUB; USPAT; EPO; JPO; DERWENT; IBM_TDB	OR	ON	2009/04/06 15:35
11	2	L10 and @ad< "20031124"	US-PGPUB; USPAT; EPO; JPO; DERWENT; IBM_TDB	OR	ON	2009/04/06 15:35
12	0	L3 and(test\$3 or inspect\$3 or examining)and(detect\$3 or determining)and(defect or flaw or fault)and joints	US-PGPUB; USPAT; EPO; JPO; DERWENT; IBM_TDB	OR	ON	2009/04/06 15:38
13	0	L10 and(detect\$3 or determining)and(defect or flaw or fault)and joints	US-PGPUB; USPAT; EPO; JPO; DERWENT; IBM_TDB	OR	ON	2009/04/06 15:38
14	1	L10 and joints	US-PGPUB; USPAT; EPO; JPO; DERWENT; IBM_TDB	OR	ON	2009/04/06 15:38

L15	4	L3 and joints	US-PGPUB; USPAT; EPO; JPO; DERWENT; IBM_TDB	OR	ON	2009/04/06 15:38
.16	1	L15 and(detect\$3 or determining)and(defect or flaw or fault)and joints	US-PGPUB; USPAT; EPO; JPO; DERWENT; IBM_TDB	OR	ON	2009/04/06 15:39
.17	1	L16 and @ad< "20031124"	US-PGPUB; USPAT; EPO; JPO; DERWENT; IBM_TDB	OR	ON	2009/04/06 15:39
.18	0	L15 and(comparision or match\$3)	US-PGPUB; USPAT; EPO; JPO; DERWENT; IBM_TDB	OR	ON	2009/04/06 15:43
19	1	L15 and thickness and measured	US-PGPUB; USPAT; EPO; JPO; DERWENT; IBM_TDB	OR	ON	2009/04/06 15:44
20	0	L19 and non-destructive	US-PGPUB; USPAT; EPO; JPO; DERWENT; IBM_TDB	OR	ON	2009/04/06 15:44
21	0	L19 and bead and angles and dimension	US-PGPUB; USPAT; EPO; JPO; DERWENT; IBM_TDB	OR	ON	2009/04/06 15:46
22	0	L19 and angles and dimension	US-PGPUB; USPAT; EPO; JPO; DERWENT; IBM_TDB	OR	ON	2009/04/06 15:46

.23	0	L19 and dimension	US-PGPUB; USPAT; EPO; JPO; DERWENT; IBM_TDB	OR	ON	2009/04/06 15:46
24	8587	nuclear adj fuel and assembly	US-PGPUB; USPAT; EPO; JPO; DERWENT; IBM_TDB	OR	ON	2009/04/06 15:56
25	0	L24 and longituduinal	US-PGPUB; USPAT; EPO; JPO; DERWENT; IBM_TDB	OR	ON	2009/04/06 15:57
26	1712	L24 and longitudinal	US-PGPUB; USPAT; EPO; JPO; DERWENT; IBM_TDB	OR	ON	2009/04/06 15:57
27	584	L24 and longitudinal adj axis	US-PGPUB; USPAT; EPO; JPO; DERWENT; IBM_TDB	OR	ON	2009/04/06 15:57
28	48	L27 and sheath	US-PGPUB; USPAT; EPO; JPO; DERWENT; IBM_TDB	OR	ON	2009/04/06 15:57
29	17	L28 and sealed and top and bottom	US-PGPUB; USPAT; EPO; JPO; DERWENT; IBM_TDB	OR	ON	2009/04/06 15:58
30	8816	L29 aqnd weld adj bead	US-PGPUB; USPAT; EPO; JPO; DERWENT; IBM_TDB	OR	ON	2009/04/06 16:03

L31	1	L29 and weld adj bead	US-PGPUB; USPAT; EPO; JPO; DERWENT; IBM_TDB	OR	ON	2009/04/06 16:04
L32	0	L31 and @ad< "20031124"	US-PGPUB; USPAT; EPO; JPO; DERWENT; IBM_TDB	OR	ON	2009/04/06 16:04
L33	11	L29 and @ad<"20031124"	US-PGPUB; USPAT; EPO; JPO; DERWENT; IBM_TDB	OR	ON	2009/04/06 16:04
_34	0	L33 and weld adj bead	US-PGPUB; USPAT; EPO; JPO; DERWENT; IBM_TDB	OR	ON	2009/04/06 16:05
35	2321	382/100,249,118.cds.	USPAT	OR	ON	2009/04/06 16:06
_37	8780	382/100,249,118,232,248,249,276,286,291,154,181,190,195,203.cds.	USPAT	OR	ON	2009/04/06 16:08
_38	0	L37 and nuclear adj fuel and assembly	US-PGPUB; USPAT; EPO; JPO; DERWENT; IBM_TDB	OR	ON	2009/04/06 16:09
_39	3	L37 and(acquiring or obtaining)near2 radiographic adj image\$1	US-PGPUB; USPAT; EPO; JPO; DERWENT; IBM_TDB	OR	ON	2009/04/06 16:10
_40	21	L37 and(acquiring or obtaining)and radiographic adj image\$1	US-PGPUB; USPAT; EPO; JPO; DERWENT; IBM_TDB	OR	ON	2009/04/06 16:10

L41	0	L40 and nuclear adj fuel	US-PGPUB; USPAT; EPO; JPO; DERWENT; IBM_TDB	OR	ON	2009/04/06 16:10
L42	0	L40 and(detect\$3 or determining)and(defect or flaw or fault)and joints	US-PGPUB; USPAT; EPO; JPO; DERWENT; IBM_TDB	OR	ON	2009/04/06 16:11
L43	8821	L40 aqnd weld adj bead	US-PGPUB; USPAT; EPO; JPO; DERWENT; IBM_TDB	OR	ON	2009/04/06 16:12
L44	0	L40 and weld adj bead	US-PGPUB; USPAT; EPO; JPO; DERWENT; IBM_TDB	OR	ON	2009/04/06 16:12
L45	0	L40 and(test\$3 or inspect\$3 or examining)and(detect\$3 or determining)and(defect or flaw or fault)and welding adj joints	US-PGPUB; USPAT; EPO; JPO; DERWENT; IBM_TDB	OR	ON	2009/04/06 16:13
_46	0	L40 and(detect\$3 or determining)and(defect or flaw or fault)and joints	US-PGPUB; USPAT; EPO; JPO; DERWENT; IBM_TDB	OR	ON	2009/04/06 16:13
L47	17	L40 and @ad<"20031124"	US-PGPUB; USPAT; EPO; JPO; DERWENT; IBM_TDB	OR	ON	2009/04/06 16:13
L48	0	L47 and weld adj bead	US-PGPUB; USPAT; EPO; JPO; DERWENT; IBM_TDB	OR	ON	2009/04/06 16:49

L49	6	L47 and angles and dimension	US-PGPUB; USPAT; EPO; JPO; DERWENT; IBM_TDB	OR	ON	2009/04/06 16:50
_50	1	L49 and thickness and measured	US-PGPUB; USPAT; EPO; JPO; DERWENT; IBM_TDB	OR	ON	2009/04/06 16:51
L51	0	L50 and porous and(areas or region)	US-PGPUB; USPAT; EPO; JPO; DERWENT; IBM_TDB	OR	ON	2009/04/06 16:53
_52	0		US-PGPUB; USPAT; EPO; JPO; DERWENT; IBM_TDB	OR	ON	2009/04/06 16:53
<u>-</u> 53	0	L50 and nuclear adj fuel	US-PGPUB; USPAT; EPO; JPO; DERWENT; IBM_TDB	OR	ON	2009/04/06 16:54
.54	7815	358/1.9,1.1,500,501,502,518,520,1.18.cds.	USPAT	OR	ON	2009/04/06 17:01
_55	1	L54 and(acquiring or obtaining)near2 radiographic adj image\$1	USPAT	OR	ON	2009/04/06 17:02
_56	1	L55 and @ad<"20031124"	USPAT	OR	ON	2009/04/06 17:03
_57	0	(non-destructive and test\$3 and nuclear adj reactor and acquiring and reference adj image and processed and unprocessed and detect adj defects).clm.	US-PGPUB	OR	ON	2009/04/06 17:06
_58	1	(non-destructive and testing and nuclear adj reactor and acquiring radiographic adj image and reference adj image and processed and unprocessed and detect adj defects).clm.	US-PGPUB	OR	ON	2009/04/06 17:07
_59	677	(non-destructive or non adj destructive) and surface adj defects	US-PGPUB; USPAT; EPO; JPO; DERWENT; IBM_TDB	OR	ON	2009/04/06 17:27

L60	2	L59 and(acquiring or obtaining)and radiographic adj image\$1	US-PGPUB; USPAT; EPO; JPO; DERWENT; IBM_TDB	OR	ON	2009/04/06 17:28
_61	2	L60 and @ad<"20031124"	US-PGPUB; USPAT; EPO; JPO; DERWENT; IBM_TDB	OR	ON	2009/04/06 17:28
_62	1	L61 and(test\$3 or inspect\$3 or examining)and(detect\$3 or determining)and(defect or flaw or fault)and welding adj joints	US-PGPUB; USPAT; EPO; JPO; DERWENT; IBM_TDB	OR	ON	2009/04/06 17:28
<u>.</u> 63	2	L61 and(test\$3 or inspect\$3 or examining)and(detect\$3 or determining)and(defect or flaw or fault)	US-PGPUB; USPAT; EPO; JPO; DERWENT; IBM_TDB	OR	ON	2009/04/06 17:29
.64	0	L63 and weld adj bead	US-PGPUB; USPAT; EPO; JPO; DERWENT; IBM_TDB	OR	ON	2009/04/06 17:29
.65	0	L63 and angles and dimension	US-PGPUB; USPAT; EPO; JPO; DERWENT; IBM_TDB	OR	ON	2009/04/06 17:29
_66	0	L63 and thickness and measured	US-PGPUB; USPAT; EPO; JPO; DERWENT; IBM_TDB	OR	ON	2009/04/06 17:29
_67	18896	"378"/\$.cds.	USPAT	OR	ON	2009/04/06 17:31
 .68	4	L67 and(non-destructive or non adj destructive)and surface adj defects	USPAT	OR	ON	2009/04/06 17:31
<u>.</u> 69	1	L68 and(acquiring or obtaining)and radiographic adj image\$1	USPAT	OR	ON	2009/04/06 17:32
_70	87931	"250"/\$.cds.	USPAT	OR	ON	2009/04/06 17:32

_71	88	L70 and(non-destructive or non adj destructive)and surface adj defects	USPAT	OR	ON	2009/04/06 17:32
.72	1	L71 and(acquiring or obtaining)and radiographic adj image\$1	USPAT	OR	ON	2009/04/06 17:32
_73	1	L72 and @ad< "20031124"	USPAT	OR	ON	2009/04/06 17:33
S1	337	non-destructive and test\$3 and nuclear adj reactor	US-PGPUB; USPAT; EPO; JPO; DERWENT; IBM_TDB	OR	ON	2009/04/06 13:38
52	2	non-destructive and test\$3 and nuclear adj reactor and radiographic and digital adj image \$1	US-PGPUB; USPAT; EPO; JPO; DERWENT; IBM_TDB	OR	ON	2009/04/06 13:39
33	10	non-destructive and test\$3 and nuclear adj reactor and radiographic adj image\$1	US-PGPUB; USPAT; EPO; JPO; DERWENT; IBM_TDB	OR	ON	2009/04/06 13:43
 Э	9	S3 and(@ad<"20031124" or @rlad<"20031124" or @prad<"20031124" or @ptad<"20031124")	US-PGPUB; USPAT; EPO; JPO; DERWENT; IBM_TDB	OR	ON	2009/04/06 13:49
55	9	S3 and @ad<"20031124"	US-PGPUB; USPAT; EPO; JPO; DERWENT; IBM_TDB	OR	ON	2009/04/06 13:50
	0	(test\$3 or inspect\$3 or examining)and(defect or flaw or fault)and welding adj joints and radiographic and digital adj image\$1	US-PGPUB; USPAT; EPO; JPO; DERWENT; IBM_TDB	OR	ON	2009/04/06 13:56
57	286	(test\$3 or inspect\$3 or examining)and(defect or flaw or fault)and radiographic and digital adj image\$1	US-PGPUB; USPAT; EPO; JPO; DERWENT; IBM_TDB	OR	ON	2009/04/06 13:57

\$8	375	(test\$3 or inspect\$3 or examining)and(detect\$3 or determining)and(defect or flaw or fault) and radiographic adj image\$1	US-PGPUB; USPAT; EPO; JPO; DERWENT; IBM_TDB	OR	ON	2009/04/06 13:58
S9	307	S8 and(@ad<"20031124" or @rlad<"20031124" or @prad<"20031124" or @prad<"20031124" or	US-PGPUB; USPAT; EPO; JPO; DERWENT; IBM_TDB	OR	ON	2009/04/06 13:58
S10	257	S8 and @ad<"20031124"	US-PGPUB; USPAT; EPO; JPO; DERWENT; IBM_TDB	OR	ON	2009/04/06 13:59
S11	75	S10 and(comparision or match\$3)and(stored or memory)	US-PGPUB; USPAT; EPO; JPO; DERWENT; IBM_TDB	OR	ON	2009/04/06 14:00
S12	0	S11 and assisting and rotating adj object and record\$3 adj image\$1 and digital adj mapp and welded adj joints	US-PGPUB; USPAT; EPO; JPO; DERWENT; IBM_TDB	OR	ON	2009/04/06 14:06
S13	0	S10 and assisting and rotating adj object and record\$3 adj image\$1 and digital adj mapp and welded adj joints	US-PGPUB; USPAT; EPO; JPO; DERWENT; IBM_TDB	OR	ON	2009/04/06 14:06
S14	375	(test\$3 or inspect\$3 or examining)and(detect\$3 or determining)and(defect or flaw or fault) and radiographic adj image\$1	US-PGPUB; USPAT; EPO; JPO; DERWENT; IBM_TDB	OR	ON	2009/04/06 14:10
S15	0	S14 and(test\$3 or inspect\$3 or examining)and(detect\$3 or determining)and(defect or flaw or fault)and radiographic adj image\$1 and welding adj joints and tubing	US-PGPUB; USPAT; EPO; JPO; DERWENT; IBM_TDB	OR	ON	2009/04/06 14:12

S16	1	or fault) and radiographic adj image\$1 and welding adj joints	US-PGPUB; USPAT; EPO; JPO; DERWENT; IBM_TDB	OR	ON	2009/04/06 14:20
S17	106	(test\$3 or inspect\$3 or examining)and(detect\$3 or determining)and(defect or flaw or fault) and welding adj joints	US-PGPUB; USPAT; EPO; JPO; DERWENT; IBM_TDB	OR	ON	2009/04/06 14:21
518	1	or fault) and radiographic adj image\$1	US-PGPUB; USPAT; EPO; JPO; DERWENT; IBM_TDB	OR	ON	2009/04/06 14:22
619	106	(test\$3 or inspect\$3 or examining)and(detect\$3 or determining)and(defect or flaw or fault) and welding adj joints	US-PGPUB; USPAT; EPO; JPO; DERWENT; IBM_TDB	OR	ON	2009/04/06 14:29
320	0	S19 and nuclear adj fuel and rods	US-PGPUB; USPAT; EPO; JPO; DERWENT; IBM_TDB	OR	ON	2009/04/06 14:30
21	348	non adj destructive and test\$3 and nuclear adj reactor	US-PGPUB; USPAT; EPO; JPO; DERWENT; IBM_TDB	OR	ON	2009/04/06 14:33
322	1	\$21 and(acquiring or obtaining)near2 radiographic adj image\$1	US-PGPUB; USPAT; EPO; JPO; DERWENT; IBM_TDB	OR	ON	2009/04/06 14:35
23	3	\$21 and(acquiring or obtaining)and radiographic adj image\$1	US-PGPUB; USPAT; EPO; JPO; DERWENT; IBM_TDB	OR	ON	2009/04/06 14:35

S24	2	S23 and @ad< "20031124"	US-PGPUB; USPAT; EPO; JPO; DERWENT; IBM_TDB	OR	ON	2009/04/06 14:36
S25	0	S24 and(comparision or match\$3)and(stored or memory)	US-PGPUB; USPAT; EPO; JPO; DERWENT; IBM_TDB	OR	ON	2009/04/06 14:36
S26	2	S24 and(comparision or match\$3)	US-PGPUB; USPAT; EPO; JPO; DERWENT; IBM_TDB	OR	ON	2009/04/06 14:37
S27	0	S26 and(test\$3 or inspect\$3 or examining)and(detect\$3 or determining)and(defect or flaw or fault)and welding adj joints	US-PGPUB; USPAT; EPO; JPO; DERWENT; IBM_TDB	OR	ON	2009/04/06 14:37
S28	0	S26 and(test\$3 or inspect\$3 or examining or detect\$3 or determining)and(defect or flaw or fault)and welding adj joints	US-PGPUB; USPAT; EPO; JPO; DERWENT; IBM_TDB	OR	ON	2009/04/06 14:38
S29	0	S26 and(test\$3 or inspect\$3 or examining or detect\$3 or determining defect or flaw or fault)and welding adj joints	US-PGPUB; USPAT; EPO; JPO; DERWENT; IBM_TDB	OR	ON	2009/04/06 14:38
S30	2	S26 and(test\$3 or inspect\$3 or examining or detect\$3 or determining defect or flaw or fault)	US-PGPUB; USPAT; EPO; JPO; DERWENT; IBM_TDB	OR	ON	2009/04/06 14:38
S31	0	S30 and thickness adj measured	US-PGPUB; USPAT; EPO; JPO; DERWENT; IBM_TDB	OR	ON	2009/04/06 14:39

332	11	S30 and thickness and measured	US-PGPUB; USPAT; EPO; JPO; DERWENT; IBM_TDB	OR	ON	2009/04/06 14:39
333	0	S32 and porous and(areas or region)	US-PGPUB; USPAT; EPO; JPO; DERWENT; IBM_TDB	OR	ON	2009/04/06 14:40
334	0	S32 and porous and(area or region)	US-PGPUB; USPAT; EPO; JPO; DERWENT; IBM_TDB	OR	ON	2009/04/06 14:40
35	0	S32 and bead	US-PGPUB; USPAT; EPO; JPO; DERWENT; IBM_TDB	OR	ON	2009/04/06 14:41
36	0	S32 and(nuclear adj fuel or rods)	US-PGPUB; USPAT; EPO; JPO; DERWENT; IBM_TDB	OR	ON	2009/04/06 14:42
37	0	S32 and(nuclear adj fuel or rod)	US-PGPUB; USPAT; EPO; JPO; DERWENT; IBM_TDB	OR	ON	2009/04/06 14:42
38	0	S32 and angles	US-PGPUB; USPAT; EPO; JPO; DERWENT; IBM_TDB	OR	ON	2009/04/06 14:43
339	0	S32 and dimension	US-PGPUB; USPAT; EPO; JPO; DERWENT; IBM_TDB	OR	ON	2009/04/06 14:44
340	4	((PHILIPPE) near2 (MAHE)).INV.	US-PGPUB; USPAT	OR	ON	2009/04/06 14:45

S41	1	S40 and(acquiring or obtaining)and radiographic adj image\$1	US-PGPUB; USPAT; EPO; JPO; DERWENT; IBM_TDB	OR	ON	2009/04/06 14:46
S42	1	S41 and(comparision or match\$3)	US-PGPUB; USPAT; EPO; JPO; DERWENT; IBM_TDB	OR	ON	2009/04/06 14:47
S43	1	S42 and(test\$3 or inspect\$3 or examining or detect\$3 or determining defect or flaw or fault)	US-PGPUB; USPAT; EPO; JPO; DERWENT; IBM_TDB	OR	ON	2009/04/06 14:47
S44	0	S43 and(@ad<"20031124" or @rlad<"20031124" or @prad<"20031124" or @prad<"20031124")	US-PGPUB; USPAT; EPO; JPO; DERWENT; IBM_TDB	OR	ON	2009/04/06 14:47
S45	0	S43 and @ad<"20031124"	US-PGPUB; USPAT; EPO; JPO; DERWENT; IBM_TDB	OR	ON	2009/04/06 14:48
S46	6	(("(6154561") or ("2001055415") or ("5999636).pn.")).PN.	US-PGPUB; USPAT; EPO; JPO; DERWENT; IBM_TDB	OR	OFF	2009/04/06 14:49
S47	0	S46 and(acquiring or obtaining)and radiographic adj image\$1	US-PGPUB; USPAT; EPO; JPO; DERWENT; IBM_TDB	OR	ON	2009/04/06 14:49
S48	6	S46 and @ad<"20031124"	US-PGPUB; USPAT; EPO; JPO; DERWENT; IBM_TDB	OR	ON	2009/04/06 14:51

4/6/09 5:33:53 PM

C:\ Documents and Settings\ SChawan\ My Documents\ EAST\ Workspaces\ 0513.wsp